

KISH P & I LOSS PREVENTION CIRCULAR KPI-LP-111-2013 (Counterfeit GMDSS Batteries)

We have -through reliable sources- become aware of non-original GMDSS batteries being promoted, sold and installed on board SOLAS convention vessels for use in GMDSS equipment required by SOLAS. In particular these counterfeit batteries are being promoted, sold and installed for use in Jotron products type Tron 40S, Tron SART, Tron SART 20 and Tron TR-20 GMDSS.

The non-original batteries are apparently being manufactured in China, labeled with Chinese text and bearing CCS approval No. CQ07T00007. It should be realized that the use of non-original (replacement) batteries in legally required GMDSS equipment on some flag vessels is not allowed, as this is considered an infringement of the type approval. Original manufacturer batteries, i.e. those indicated on the module B certificate of the GMDSS

equipment (e.g. EPIRB or SART), shall always be used.

Furthermore, non-original (replacement) batteries have been shown to be of inferior quality and the use of them may result in safety risk and/or the failure of the GMDSS equipment to function properly in a distress situation.

Cospas-Sarsat, who are responsible for approving EPIRBs to operate within the Cospas-Sarsat satellite-system have also confirmed that the use of non-original manufacturer batteries for Tron 40S do not comply to Certificate/TAC no. 95 and therefore cannot be considered as a Cospas-Sarsat approved EPIRB.

It is very important to bring this information to the attention of members, crews, surveyors and other relevant employees and parties, and to take the necessary corrective measures as/when the occasion arises.





Page 1 of 1

Announcing that our expertise have taken utmost care for the authenticity of the information in this document; Providing guidelines & notices; Permitting the usage of the info & data in training, familiarization and any other possible and legitimate loss prevention activities; KPI accepts no Liabilities or claims whatsoever arising from or related to the inadequate use or incorrect construing of the furnished knowledge and thus advises all recipients to Endeavour the necessary Due Diligence in carrying out their management & operational activities upon and through which the KPI club is providing support & assistance