

KISH P & I LOSS PREVENTION CIRCULAR KPI-LP-121-2013 (Risks involved with Dropping of an Anchor Underway)

Official report edited from The Dutch Safety Board

Description of the incident:

In calm weather and good visibility, a cargo vessel under pilotage while departing port was overtaking a tug towing a pontoon. The cargo vessel's electrical needs at the time were being supplied via the shaft generator. Both of the ship's service generators were shut down to save on fuel.

While overtaking the pontoon, the cargo vessel's main engine suddenly failed. Since the electrical systems on board the vessel were linked to the main engine via the shaft generator, the electricity failed as well and for a short period of time the vessel suffered a blackout. During the blackout, the rudder unexpectedly turned to port, causing the vessel to deviate sharply from its course and toward the tug and tow. In order to prevent a collision, the captain, on VHF radio, ordered the anchor let go. As there were crew members on deck at the time, the anchor was let go very guickly after the order - within 15 seconds. At the time the anchor was let go the cargo vessel still had a speed over ground (SOG) of 7.5 knots.

Despite the attempts by the AB to secure the winch brake, the anchor chain continued to run out. The last length of chain had broken loose from the chain locker, and the AB was hit and fatally injured by the bitter end.

The cargo vessel collided with the pontoon almost simultaneously with the breaking free of the anchor chain. Both vessels sustained limited damage as a result of the collision.

Lessons learned:

1-The use of the anchor to slow down the ship in an emergency:

IACS stipulates that an anchor must be constructed in such a way that it is suitable to anchor a ship temporarily in 'moderate' ambient conditions. The anchor gear is not designed to stop a ship. Anchoring at high speed is an extremely risky operation that may result in fatal injuries to crew members and serious damage to the ship. Such a manoeuvre should only be considered in an emergency. The captain. extreme in consultation with the bridge team, should assess whether the potential benefits of manoeuvre outweighs such а the substantial risks for the crew and ship.

2-The need for uninterrupted power supply when sailing in confined waters: Sailing in narrow waters entails increased risks of collision or grounding. Therefore, prior to commencing a passage in confined waters, a risk analysis should be carried out (or consulted) as part of the Safety Management System in order to verify that back-up systems are instantly available. Uninterrupted power supply in confined waters is essential in order to guarantee a ship's manoeuvrability and should be considered a best practice.

Announcing that our expertise have taken utmost care for the authenticity of the information in this document; Providing guidelines & notices; Permitting the usage of the info & data in training, familiarization and any other possible and legitimate loss prevention activities; KPI accepts no Liabilities or claims whatsoever arising from or related to the inadequate use or incorrect construing of the furnished knowledge and thus advises all recipients to Endeavour the necessary Due Diligence in carrying out their management & operational activities upon and through which the KPI club is providing support & assistance.